## DIVISION OF THE STATE FIRE MARSHALL BUREAU OF FIRE PREVENTION BOILER SAFETY PROGRAM

DEC 0 6 2018

This inspection is intended for your safety and the safety of the citizens of Florida. Your cooperation is greatly appreciated.

## **Boiler - Fired Pressure Vessel report of Inspection**

Date Inspected 11/30/2018	Cert. Exp Date	Certificate Posted	Follow Up	nspection  No	Jurisdiction 019351	on Number	Nat'l Bd. N <b>5133</b>		ther No. 4S431570 (#2)	
Owner South Miami Hospital					Nature Of Business General Medical and Surgical			nspection Ext	Cert Inspection  Yes No	
Owner Street Address 6200 SW 73rd St				Owner City South Miami				ate	Zip 33143-4679	
User Name - Object Location South Miami Hospital				Specific Location in Plant BLRM - 2nd FL			Ob <b>Mi</b>	Object Location - County  Miami-Dade		
User Street Address 6200 SW 73rd St					User City South Miami			ate -	Zip 33143-4679	
Type . Water Tube			Year Built 2003	Manufacturer <b>Miura</b>						
Use Process	Fuel Method of Firing Natural Gas Automatic			ring	g Pressure Gage Tested ☐ Yes ✓ No					
Pressure This Ins	/alves Set At   Total Capacity   psi   4234 LB/HR				Heating Surface and/or BTU 199 sq ft / 2588000 BTU/hr					
Is condition of object such that a certificate may be issued? (If No, explain fully under condition)						lydro Test Yes	PSI	DATE	√ No	
CONDITIONS: With respect to the internal surface, describe and state location of any scale, oil or other deposits. Give location and extent of any corrosion and state whether active or inactive. State location and extent of any erosion, grooving, bulging, warping, cracking or similar condition. Report on any defective rivets, bowed, loose or broken stays. State condition of all tubes, tube ends, coils, nipples, etc. Describe any adverse conditions with respect to pressure gage, water column, gage glass, gage cocks, safety valves, etc. Report conditions of setting, linings, baffles, supports, etc. Describe any major changes or repairs made since last inspection.  Internal inspection performed, scale considered minimal, watersides were free of visible surface defects or cracks, no leaks noted. All associated piping, fittings, attachments and supports were found to be in good condition. Firesides showed no signs of overheating and the refractory was found to be in good condition. LWCO's were disassembled and inspected with no abnormal conditions noted.  Boiler safety valve found leaking at weephole. Violation submitted.  Violation-FL-1.4 — The safety valve associated with boiler numbered 019531 was found to be leaking at the weephole. This seat leakage can result in accumulation of deposits on the seating surface, which may impeade proper operation of the valve in the event of an overpressure condition in the boiler.										
REQUIREMENTS: (List of Code Violations)  Replace the safety valve with an ASME/NB Section 1, V stamped valve having a set pressure not exceeding 150 PSI and minimum relieving capacity of 2588 LB/HR.										
Name and Title of Person To Whom Requirements Were Explained Oneil Rivera, Plant Technician										
HEREBY CERTI	FY THIS IS A TRU	E REPORT OF MY	INSPECTION							
Inspector Name	· · · · · · · · · · · · · · · · · · ·	Ident. No.			l i	Employed By			Ident. No.	
Joseph Guinto		FL-127 N	IB-11858			FM Global			30199775	
	·								<del></del>	

D14-379 10/01/2000