DIVISION OF THE STATE FIRE MARSHALL
BUREAU OF FIRE PREVENTION
BOILER SAFETY PROGRAM

This inspection is intended for your safety and the safety of the citizens of Florida. Your cooperation is greatly appreciated.

Boiler - Fired Pressure Vessel report of Inspection

Date Inspected	Cert. Exp Date	Certificate Posted	Follow Up Inspection	Jurisdiction Number	Nat'l Bd. No.	Other No.
10/06/2021		☑ Yes ☐ No	☐ Yes ☑ No	023104	19613	19613

Owner	Owner Email	Kind of Inspection	Cert Inspection
Florida School for the Deaf and Blind (SOF)	peacockg@fsdbk12.org	☑ Int ☐ Ext	☐ Yes ☑ No

Owner Street Address	Owner City	State	Zip
207 San Marco Ave	St Augustine	FL	32084-2762

User Name - Object Location	Nature Of Business	Object Location - County
Florida School for the Deaf and Blind (SOF)	Schools and Educational	Saint Johns

User Street Address	User City	State	Zip
207 San Marco Ave	St Augustine	FL	32084-2762

Type	ASME Code Stamp	Year Built	Manufacturer
Electric	S	2011	Precision

Specific Location in Plant	Use	Fuel	Method of Firing	Pressure Gage Tested
Kirk Memorial Room 124	Process	Electric	Electricity	☐ Yes ☑ No

Pressure Allowed	This Inspection	Prev. Inspection	Safety Relief Valves Set At	Total Capacity	Heating Surface and/or BTU
	100 psi	100 psi	100 psi	644 LB/HR	630 BTU/hr

Is condition of object such that a certificate may be issued? (If No, explain fully under condition) ☐ Yes ☑ No

Hydro Test ☐ Yes _____ PSI DATE _____ ☑ No

CONDITIONS: With respect to the internal surface, describe and state location of any scale, oil or other deposits. Give location and extent of any corrosion and state whether active or inactive. State location and extent of any erosion, grooving, bulging, warping, cracking or similar condition. Report on any defective rivets, bowed, loose or broken stays. State condition of all tubes, tube ends, coils, nipples, etc. Describe any adverse conditions with respect to pressure gage, water column, gage glass, gage cocks, safety valves, etc. Report conditions of setting, linings, baffles, supports, etc. Describe any major changes or repairs made since last inspection.

Internal inspection found only minor scale formation of the boiler. Low water cutout chamber was clean. Violation FL-1.3.13 PRD IMPROPER DISCHARGE - Relief valve discharge line is tied into return tank and condensate tank vent line. – -FL-1.3.13 PRD IMPROPER DISCHARGE

REQUIREMENTS: (List of Code Violations)

-REF: 2017 EDITION NATIONAL BOARD INSPECTION CODE PARAGRAPH RB-3540 (g): IMPROPER PRESSURE RELIEF DEVICE DISCHARGE

Name and Title of Person To Whom Requirements Were Explained
Greg Peacock

I HEREBY CERTIFY THIS IS A TRUE REPORT OF MY INSPECTION

Inspector Name	Ident. No.	Employed By	Ident. No.
Charles J. Schindler	FL-606 NB-11697	Liberty Mutual Insurance Co	30199794

D14-379
10/01/2000