DIVISION OF THE STATE FIRE MARSHALL BUREAU OF FIRE PREVENTION BOILER SAFETY PROGRAM

This inspection is intended for your safety and the safety of the citizens of Florida. Your cooperation is greatly appreciated.

DEC 0 6 2019 **Boiler - Fired Pressure Vessel report of Inspection** Date Inspected Cert. Exp Date Certificate Posted Follow Up Inspection Jurisdiction Number Nat'l Bd. No. Other No. 11/22/2019 019351 ✓ Yes ∏No 5133 Yes **✓** No 64\$431570 (#2) Owner Nature Of Business Kind of Inspection Cert Inspection South Miami Hospital General Medical and Surgical **✓** Int Ext ✓ Yes No Owner Street Address Owner City State 6200 SW 73rd St FL South Miami 33143-4679 User Name - Object Location Specific Location in Plant Object Location - County South Miami Hospital BLRM - 2nd FL Miami-Dade User Street Address User City State 6200 SW 73rd St South Miami FL 33143-4679 Tyne Year Built Manufacturer **Water Tube** 2003 Miura Use Fuel Method of Firing Pressure Gage Tested **Process** Natural Gas Automatic Yes ✓ No Pressure This Inspection Safety Relief Valves Set At Prev. Inspection Total Capacity Heating Surface and/or BTU Allowed 170 psi 170 150 psi 4234 LB/HR 199 sq ft / 2588000 BTU/hr ls condition of object such that a certificate may be issued? Hydro Test (If No, explain fully under condition) Yes PSI DATE No □Yes **✓** No CONDITIONS: With respect to the internal surface, describe and state location of any scale, oil or other deposits. Give location and extent of any corrosion and state whether active or inactive. State location and extent of any erosion, grooving, bulging, warping, cracking or similar condition. Report on any defective rivets, bowed, loose or broken stays. State condition of all tubes, tube ends, coils, nipples, etc. Describe any adverse conditions with respect to pressure gage, water column, gage glass, gage cocks, safety valves, etc. Report conditions of setting, linings, baffles, supports, etc. Describe any major changes or repairs made since last inspection. Internal inspection performed, scale considered minimal, watersides were free of visible surface defects or cracks, no leaks noted. All associated piping, fittings, attachments and supports were found to be in good condition. LWCO's were disassembled and inspected with no abnormal conditions noted. Safety relief device manually tested by inhouse staff. UM Group was the boiler concerned used during this inspection. Ok to issue certificate. **REQUIREMENTS:** (List of Code Violations) None Required

Employed By

FM Global

Ident. No.

30275196

D14-379 10/01/2000

Joseph Guinto

Inspector Name

Danny Ramirez, Operator

Name and Title of Person To Whom Requirements Were Explained

HEREBY CERTIFY THIS IS A TRUE REPORT OF MY INSPECTION

ldent. No.

FL-127 NB-11858