DIVISION OF THE STATE FIRE MARSHALL BUREAU OF FIRE PREVENTION BOILER SAFETY PROGRAM

This inspection is intended for your safety and the safety of the citizens of Florida. Your cooperation is greatly appreciated.

Boiler - Fired Pressure Vessel report of Inspection

	1		T=		-				
Date Inspected 11/19/2020	Cert. Exp Date	Certificate Posted V Yes No	Follow Up	Inspection Jurisdiction Number V No 019351		Nat'l Bd 5133	Nat'l Bd. No. Other No. 64S431570 (#2)		
Owner			Owner E					of Inspection	Cert Inspection
South Miami Hos Owner Street Addr	orr@baptisthealth.net			<u> </u>	nt Ext State	✓ Yes No Zip			
6200 SW 73rd St			South Miami				FL	33143-4679	
User Name - Object Location				Nature Of Business				Object Locat	
South Miami Hospital				General Medical and Surgical Miami-Dade					
User Street Address			User City				State	Zip	
6200 SW 73rd St			l	South Miam				FL	33143-4679
Type Water Tube		ASME Code Stamp S	Year Built 2003	Manufacturer Miura					
Specific Location in		Use		Fuel	N	Method of Fir	ing	Pressur	e Gage Tested
BLRM - 2nd FL		Process		Natural Gas	. 4	Automatic			Yes ✓ No
Pressure This Ins Allowed 170			fety Relief V 50	alves Set At psi	Total Capa			-	Surface and/or BTU
	<u>'</u>	tificate may be issued?		ры	4234 LE	o Test		199 sq f	t / 2588000 BTU/hr
(If No, explain fully		indute may be located.	✓ Ye	s No	1	es	PS	I DATE	✓ No
CONDITIONS: With respect to the internal surface, describe and state location of any scale, oil or other deposits. Give location and extent of any corrosion and state whether active or inactive. State location and extent of any erosion, grooving, bulging, warping, cracking or similar condition. Report on any defective rivets, bowed, loose or broken stays. State condition of all tubes, tube ends, coils, nipples, etc.									
	Describe any adv	t on any derective rivets, /erse conditions with res ing, linings, baffles, supp	pect to press	ure gage, wate	r column, ga	ige glass, gag	ge cocks,	safety valves	, etc. Report
	conditions of setti	ing, inings, bames, supp	oris, etc. De	escribe arry maj	or changes t	oi repairs ma	ue sirice	iasi irispeciioi	1.
Internal inspe	ction performe	ed, scale considere	ed minima	al, waterside	es were fr	ree of visil	ble sur	face defec	ts or cracks, no
		piping, fittings, att							
noted. LWCO's were disassembled and inspected with no abnormal conditions noted. Safety valve manually tested									
by contractor	during startup	 UM Group was t 	he boiler	concern us	ed for the	e startup.	Ok to i	ssue certi	ficate.
REQUIREMEN	ITS: (List of Code	Violations)							
		violationo							
None Require	d								
Name and Title of James Sosa, Tec		Requirements Were Ex	xplained						
· ·		JE REPORT OF MY IN	SPECTION						
Inspector Name		Ident. No.							
•		luent. No.			Emr	oloyed By			Ident. No.