

DIVISION OF STATE FIRE MARSHAL BUREAU OF FIRE PREVENTION BOILER SAFETY PROGRAM

Boiler-Fired Pressure Vessel REPORT OF INSPECTION

This inspection is intended for your safety and the safety of the citizens of Florida. Your cooperation is greatly appreciated.									
DATE INSPECTED	DATE INSPECTED CERT EXP DATE CERT POSTED		D FOLLOW UP ?	JURISDICTION NUMBER		NATL BOARD NO OTHER NO			
02/23/2023		● Yes ○ No	OYes ● No	FL018817		11405			
OWNER				NATURE OF BUSINESS		KIND OF INSP.		CERT INSP ?	
XENIA HOTEL & RESORTS, INC.				HOTELS & MOTELS		○INT ● EXT		● Yes ○ No	
OWNER STREET ADDRESS				OWNERS CITY		STATE ZIP		ZIP	
200 S ORANGE AVE STE 2700				ORLANDO	RLANDO			32801	
USER NAME - OBJECT LOCATION				SPECIFIC LOCATION IN PLANT OB			OBJECT LOCATION - COUNTY		
GRAND CYPRESS				STEAM BLRM ORAN			ANGE		
LOCATION STREET ADDRESS				LOCATION CITY		STATE		ZIP	
1 GRAND CYPRESS BLVD				ORLANDO FL				32836	
TYPE YEAR BUILT				MANUFACTURER					
✓ FT WT	CI	OTHER	2009	SELLERS					
USE				FUEL METHOD		O OF FIRING F		PRESSURE TESTED	
☐ POWER ☑ PROCESS☐ STM HTG ☐ HWH ☐ HWS ☐ OTHE			Natural Gas	Burner			○Yes • No		
PRESSURE ALLOWED SAFETY - RELIEI				F VALVES			OBJECT CAPACITY		
THIS INSPECTION 150 PREV INSP 150			SET AT 150	T 150 TOTAL CAPACITY 4,238 Po		nds Per Hour 2,760,000 BTUs		000 BTUs	
IS CONDITION OF OBJECT SUCH THAT A CERTIFICATE MAY BE ISSUED ? HYDRO TEST									
Yes ● No (IF NO EXPLAIN FULLY UNDER CONDITIONS)				○Yes ● No PSI	○Yes ● No PSI Date				
CONDITIONS: With respect to the internal surface, describe and state location of any scale, oil or other deposits. Give location and extent of any corrosion and state whether active or inactive. State location and extent of any erosion, grooving, bulging, warping, cracking or similar condition. Report on any defective rivets, bowed, loose or broken stays. State condition of all tubes, tube ends, coils, nipples, etc. Describe any adverse conditions with respect to pressure gage, water column, gage glass, gage cocks, safety valves, etc. Report condition of setting, linings, baffles, supports, etc. Describe any major changes or repairs made since last inspection. DURING THE EXTERNAL INSERVICE INSPECTION THE SAFETY RELEIF VALVE WAS NOT ABLE TO BE MANUALLY LIFTED CUSTOMER ADVISED AND ACCEPTED A VOLUNTARY SHITDOWN OF BOILER UNTIL NEW RELEIF VALVE CAN BE INSTALLED. BOILER SCHEDULED FOR INTERNAL & FOLLOW UP INSPECTION ON MARCH 1, DURING WHICH CUSTOMER WILL HAVE NEW SAFETY VALVE BOILER TO BE SHUT DOWN UNTIL THEN.									
REQUIREMENTS: (List Code Violations) 21-1.1									
NAME AND TITLE OF PERSON TO WHOM REQUIREMENTS WERE EXPLAINED MIKE CARDWELL CONTACT PHONE (407) 284-0652 THEREBY CERTIFY THIS IS A TRUE REPORT OF MY INSPECTION									
INSPECTOR NAME	Bob Voisinet								
SIGNATURE OF INS	PECTOR	IDEN	IT. NO	EMPLOYED BY					

HARTFORD STEAM BOILER INSPECTION AND INSURANCE COMPANY 9265

21-000887

DI4-379, 10-1-2000 Quet a Valuit