

**DIVISION OF THE STATE FIRE MARSHALL
BUREAU OF FIRE PREVENTION
BOILER SAFETY PROGRAM**

This inspection is intended for your safety and the safety of the citizens of Florida. Your cooperation is greatly appreciated.

Boiler - Fired Pressure Vessel report of Inspection


Date Inspected 01/16/2015	Cert. Exp Date	Certificate Posted <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Follow Up Inspection <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Jurisdiction Number 015166	Nat'l Rd. No. 5167	Other No. Hollywood
Owner Hollywood Studio Theme Park				Nature Of Business Amusement and Recreation	Kind of Inspection <input checked="" type="checkbox"/> Int <input type="checkbox"/> Ext	Cert Inspection <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Owner Street Address 271 N World Drive				Owner City Lake Buena Vista	State FL	Zip 32830
User Name - Object Location Hollywood Studio Theme Park				Specific Location in Plant Epic Theatre	Object Location - County Orange	
User Street Address 271 N World Dr.				User City Lake Buena Vista	State FL	Zip 32830-1000
Type Fire Tube			Year Built 1998	Manufacturer Hurst		
Use Process				Fuel Natural Gas	Method of Firing Automatic	Pressure Gage Tested <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Pressure Allowed	This Inspection 150 psi	Prev. Inspection 150 psi	Safety Relief Valves Set At 150 psi	Total Capacity 1651 LB/HR	Heating Surface and/or BTU 55 sq ft	
Is condition of object such that a certificate may be issued? (If No, explain fully under condition)				Hydro Test <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No PSI DATE <input checked="" type="checkbox"/> No		

CONDITIONS: With respect to the internal surface, describe and state location of any scale, oil or other deposits. Give location and extent of any corrosion and state whether active or inactive. State location and extent of any erosion, grooving, bulging, warping, cracking or similar condition. Report on any defective rivets, bowed, loose or broken stays. State condition of all tubes, tube ends, coils, nipples, etc. Describe any adverse conditions with respect to pressure gage, water column, gage glass, gage cocks, safety valves, etc. Report conditions of setting, linings, baffles, supports, etc. Describe any major changes or repairs made since last inspection.

The boiler is satisfactory on this internal inspection

REQUIREMENTS: (List of Code Violations)

None Required



Name and Title of Person To Whom Requirements Were Explained
Mr. Richard McArthur, Planned Work Specialist

I HEREBY CERTIFY THIS IS A TRUE REPORT OF MY INSPECTION

Inspector Name Richard L Mork	Ident. No. FL-555 NB-9759 A	Employed By FM Global	Ident. No. 30199775
---	---------------------------------------	---------------------------------	-------------------------------

**D14-379
10/01/2000**