

**DIVISION OF THE STATE FIRE MARSHALL
BUREAU OF FIRE PREVENTION
BOILER SAFETY PROGRAM**

This inspection is intended for your safety and the safety of the citizens of Florida. Your cooperation is greatly appreciated.

Boiler - Fired Pressure Vessel Change of Status

Date Inspected 08/08/2016	Cert. Exp Date 01/15/2017	Certificate Posted <input type="checkbox"/> Yes <input type="checkbox"/> No	Owner No.	Jurisdiction Number 015166	Nat'l Bd. No. 5167	Other No. Hollywood
Owner Hollywood Studio Theme Park			Nature of Business Amusement and Recreation		Kind of Inspection <input type="checkbox"/> Int <input type="checkbox"/> Ext	Cert Inspection <input type="checkbox"/> Yes <input type="checkbox"/> No
Owner Street Address 271 N World Drive			Owner City Lake Buena Vista		State FL	Zip 32830
User Name - Object Location Hollywood Studio Theme Park			Specific Location in Plant Epic Theatre		Object Location - County Orange	
User Street Address 271 N World Dr.			User City Lake Buena Vista		State FL	Zip 32830-1000
Type Fire Tube		Year Built 1998	Manufacturer Hurst			
Use Process		Fuel Natural Gas	Method of Firing Automatic		Pressure Gage Tested <input type="checkbox"/> Yes <input type="checkbox"/> No	
Pressure Allowed	This Inspection psi	Prev. Inspection psi	Safety Relief Valves Set At psi	Total Capacity	Heating Surface and/or BTU 55 sq ft	
Is condition of object such that a certificate may be issued? (If No, explain fully under condition)				Hydro Test <input type="checkbox"/> Yes <input type="checkbox"/> No		
				PSI DATE <input type="checkbox"/> No		
<p>CONDITIONS: With respect to the internal surface, describe and state location of any scale, oil or other deposits. Give location and extent of any corrosion and state whether active or inactive. State location and extent of any erosion, grooving, bulging, warping, cracking or similar condition. Report on any defective rivets, bowed, loose or broken stays. State condition of all tubes, tube ends, coils, nipples, etc. Describe any adverse conditions with respect to pressure gage, water column, gage glass, gage cocks, safety valves, etc. Report conditions of setting, linings, baffles, supports, etc. Describe any major changes or repairs made since last inspection.</p> <p>Object status changed from A - Active to R - Removed. Boiler has been scrapped and is no longer in service.</p>						
<p>REQUIREMENTS: (List of Code Violations)</p> <div style="text-align: right; font-size: 2em; font-weight: bold; margin-top: 20px;"> RECEIVED AUG 22 2016 BY: _____ </div>						
Name and Title of Person to Whom Requirements Were Explained						
I HEREBY CERTIFY THIS IS A TRUE REPORT OF MY INSPECTION <i>Joseph C. Guinto</i>						
Inspector Name Joseph Guinto		Ident. No. FL-127 NB-11858		Employed By FM Global		Ident. No. 30199775