



**DIVISION OF STATE FIRE MARSHAL
BUREAU OF FIRE PREVENTION
BOILER SAFETY PROGRAM**

JUN 27 2018

**Boiler-Fired Pressure Vessel
REPORT OF INSPECTION**

This inspection is intended for your safety and the safety of the citizens of Florida. Your cooperation is greatly appreciated.

DATE INSPECTED 06/05/2018	CERT EXP DATE	CERT POSTED <input checked="" type="radio"/> YES <input type="radio"/> NO	FOLLOW UP? <input type="radio"/> YES <input checked="" type="radio"/> NO	JURISDICTION NUMBER FL069728	NATL BOARD NO 24629	OTHER NO
OWNER MADONNA PTAK REHAB CENTER				NATURE OF BUSINESS CONVALESCENT & NURSING HOM	KIND OF INSP. <input type="radio"/> INT <input checked="" type="radio"/> EXT	CERT INSP? <input checked="" type="radio"/> YES <input type="radio"/> NO
OWNER STREET ADDRESS 400 CORBETT ST				OWNERS CITY CLEARWATER	STATE FL	ZIP 33756
USER NAME - OBJECT LOCATION MADONNA PTAK REHAB CENTER				SPECIFIC LOCATION IN PLANT BLRM	OBJECT LOCATION - COUNTY PINELLAS	
LOCATION STREET ADDRESS 400 CORBETT ST				LOCATION CITY CLEARWATER	STATE FL	ZIP 33756
TYPE <input type="checkbox"/> FT <input checked="" type="checkbox"/> WT <input type="checkbox"/> CI <input type="checkbox"/> OTHER			YEAR BUILT 1992	MANUFACTURER LOCH		
USE <input type="checkbox"/> POWER <input type="checkbox"/> PROCESS <input type="checkbox"/> STEAM HTG <input type="checkbox"/> HWH <input checked="" type="checkbox"/> HWS <input type="checkbox"/> OTHER			FUEL Natural Gas	METHOD OF FIRING Burner	PRESSURE TESTED <input type="radio"/> YES <input checked="" type="radio"/> NO	
PRESSURE ALLOWED THIS INSPECTION 160		SAFETY - RELIEF VALVES SET AT 150			TOTAL CAPACITY 1912 Pounds Per Hour	
PREV INSP 160					OBJECT CAPACITY 87 sf Heating Surface	
IS CONDITION OF OBJECT SUCH THAT A CERTIFICATE MAY BE ISSUED? <input type="radio"/> YES <input checked="" type="radio"/> NO (IF NO EXPLAIN FULLY UNDER CONDITIONS)				HYDRO TEST <input type="radio"/> YES <input checked="" type="radio"/> NO PSI DATE		

CONDITIONS: With respect to the internal surface, describe and state location of any scale, oil or other deposits. Give location and extent of any corrosion and state whether active or inactive. State location and extent of any erosion, grooving, bulging, warping, cracking or similar condition. Report on any defective rivets, bowed, loose or broken stays. State condition of all tubes, tube ends, coils, nipples, etc. Describe any adverse conditions with respect to pressure gage, water column, gage glass, gage cocks, safety valves, etc. Report condition of setting, linings, baffles, supports, etc. Describe any major changes or repairs made since last inspection.

NEEDS NEW PRESSURE GAGE WITH A PROPER RANGE.

REQUIREMENTS: (List Code Violations)

FL-7.5.1 - PRESSURE GAGE HAS AN INADEQUATE RANGE.

NAME AND TITLE OF PERSON TO WHOM REQUIREMENTS WERE EXPLAINED

GEORGE WELLS

CONTACT PHONE (727) 462-7600

THEREBY CERTIFY THIS IS A TRUE REPORT OF MY INSPECTION

INSPECTOR NAME Daniel Humenick

SIGNATURE OF INSPECTOR

IDENT. NO

EMPLOYED BY

518

HARTFORD STEAM BOILER INSPECTION AND INSURANCE COMPANY 9265

Daniel B. Humenick