

**DIVISION OF THE STATE FIRE MARSHALL
BUREAU OF FIRE PREVENTION
BOILER SAFETY PROGRAM**

This inspection is intended for your safety and the safety of the citizens of Florida. Your cooperation is greatly appreciated.

Boiler - Fired Pressure Vessel report of Inspection

Date Inspected 03/23/2021	Cert. Exp Date	Certificate Posted <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Follow Up Inspection <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Jurisdiction Number 124839	Nat'l Bd. No. 126872	Other No.	
Owner Orlando Sportsplex			Owner Email		Kind of Inspection <input type="checkbox"/> Int <input checked="" type="checkbox"/> Ext		Cert Inspection <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Owner Street Address 8701 Maitland Summit Blvd			Owner City Orlando		State FL	Zip 32810-5915	
User Name - Object Location Orlando Sportsplex			Nature Of Business Professional Sports Clubs and		Object Location - County Orange		
User Street Address 8701 Maitland Summit Blvd.			User City Orlando		State FL	Zip 32810-5915	
Type Water Tube	ASME Code Stamp HLW	Year Built 2009	Manufacturer PVI Industries				
Specific Location in Plant Skating Rink Mechanical Room		Use Hot Water Supply	Fuel Natural Gas	Method of Firing Automatic	Pressure Gage Tested <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		
Pressure Allowed 150	This Inspection 150 psi	Prev. Inspection 150 psi	Safety Relief Valves Set At 150 psi	Total Capacity 3085000 BTU/HR	Heating Surface and/or BTU 800000 BTU/hr		
Is condition of object such that a certificate may be issued? (If No, explain fully under condition)				Hydro Test <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			

CONDITIONS: With respect to the internal surface, describe and state location of any scale, oil or other deposits. Give location and extent of any corrosion and state whether active or inactive. State location and extent of any erosion, grooving, bulging, warping, cracking or similar condition. Report on any defective rivets, bowed, loose or broken stays. State condition of all tubes, tube ends, coils, nipples, etc. Describe any adverse conditions with respect to pressure gage, water column, gage glass, gage cocks, safety valves, etc. Report conditions of setting, linings, baffles, supports, etc. Describe any major changes or repairs made since last inspection.

- Florida Administrative Code Rule 69A-51.005(14); Boiler is not in operation.

REQUIREMENTS: (List of Code Violations)

Return the boiler to good operating condition or disconnect water lines, gas lines and electrical. Call inspector to re-inspect operating boiler or for inspection after disconnecting the boiler so it may be struck from the roles of active boilers.

Name and Title of Person To Whom Requirements Were Explained
Mike Angevine - Property Team Leader

I HEREBY CERTIFY THIS IS A TRUE REPORT OF MY INSPECTION

Inspector Name Henry Torres	Ident. No. FL-1641 NB-15428	Employed By OneCIS Insurance Company	Ident. No. 30284268
---------------------------------------	---------------------------------------	--	-------------------------------

**D14-379
10/01/2000**