

**DIVISION OF THE STATE FIRE MARSHALL
BUREAU OF FIRE PREVENTION
BOILER SAFETY PROGRAM**

This inspection is intended for your safety and the safety of the citizens of Florida. Your cooperation is greatly appreciated.

Boiler - Fired Pressure Vessel Change of Status

Date Inspected 09/21/2022	Cert. Exp Date 09/09/2022	Certificate Posted <input type="checkbox"/> Yes <input type="checkbox"/> No	Owner No.	Jurisdiction Number 004721	Nat'l Bd. No. 9964	Other No.	
Owner Tailored Brands Inc			Nature of Business Retail		Kind of Inspection <input type="checkbox"/> Int <input type="checkbox"/> Ext		Cert Inspection <input type="checkbox"/> Yes <input type="checkbox"/> No
Owner Street Address 6100 Stevenson Blvd Bldg B			Owner City Fremont		State CA	Zip 94538-2490	
User Name - Object Location Men's Wearhouse #3319			Specific Location in Plant SHOP		Object Location - County Hillsborough		
User Street Address 8009 Citrus Park Dr			User City Tampa		State FL	Zip 33625-3001	
Type Electric		Year Built 2006	Manufacturer Pacific				
Use Process		Fuel Electric	Method of Firing Electricity		Pressure Gage Tested <input type="checkbox"/> Yes <input type="checkbox"/> No		
Pressure Allowed	This Inspection psi	Prev. Inspection psi	Safety Relief Valves Set At psi	Total Capacity		Heating Surface and/or BTU 61000 BTU/hr	

Is condition of object such that a certificate may be issued?
(If No, explain fully under condition) ☐ Yes ☐ No

Hydro Test ☐ Yes ☐ No PSI DATE ☐ No

CONDITIONS: With respect to the internal surface, describe and state location of any scale, oil or other deposits. Give location and extent of any corrosion and state whether active or inactive. State location and extent of any erosion, grooving, bulging, warping, cracking or similar condition. Report on any defective rivets, bowed, loose or broken stays. State condition of all tubes, tube ends, coils, nipples, etc. Describe any adverse conditions with respect to pressure gage, water column, gage glass, gage cocks, safety valves, etc. Report conditions of setting, linings, baffles, supports, etc. Describe any major changes or repairs made since last inspection.

Object status changed from R - Removed to Boiler Disconnected.

REQUIREMENTS: (List of Code Violations)

Name and Title of Person to Whom Requirements Were Explained

I HEREBY CERTIFY THIS IS A TRUE REPORT OF MY INSPECTION

Inspector Name Robert Twyford	Ident. No. FL-20-000935 NB-10124	Employed By XL Insurance America, Inc.	Ident. No. 30199785
---	--	--	-------------------------------