

**DIVISION OF THE STATE FIRE MARSHALL  
BUREAU OF FIRE PREVENTION  
BOILER SAFETY PROGRAM**

This inspection is intended for your safety and the safety of the citizens of Florida. Your cooperation is greatly appreciated.

**Boiler - Fired Pressure Vessel report of Inspection**

|   |                                   |   |   |   |   |  |
|---|-----------------------------------|---|---|---|---|--|
| Date Inspected<br><b>03/15/2023</b>   | Cert. Exp Date                    | Certificate Posted<br><input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | Follow Up Inspection<br><input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | Jurisdiction Number<br><b>019808</b>  | Nat'l Bd. No.<br><b>12569</b>   | Other No.<br><b>OL102888</b>   |
| Owner<br><b>St. Anthony's Hospital</b>  |                                   |   | Owner Email<br><b>william.shumaker@baycare.org</b>  |   | Kind of Inspection<br><input type="checkbox"/> Int <input checked="" type="checkbox"/> Ext  | Cert Inspection<br><input checked="" type="checkbox"/> Yes <input type="checkbox"/> No |
| Owner Street Address<br><b>1200 7th Ave N</b>   |                                   |   | Owner City<br><b>St Petersburg</b>  |   | State<br><b>FL</b>  | Zip<br><b>33705-1300</b>   |
| User Name - Object Location<br><b>St. Anthony's Hospital</b>  |                                   |   | Nature Of Business<br><b>Nonclassifiable Establishments</b>                                 |   | Object Location - County<br><b>Pinellas</b>   |  |
| User Street Address<br><b>1200 7th Ave N</b>  |                                   |   | User City<br><b>St Petersburg</b>   |   | State<br><b>FL</b>  | Zip<br><b>33705-1300</b>   |
| Type<br><b>Fire Tube</b>  | ASME Code Stamp<br><b>S</b>       | Year Built<br><b>2003</b>   | Manufacturer<br><b>Cleaver Brooks</b>   |   |   |  |
| Specific Location in Plant<br><b>BLR RM</b>   |                                   | Use<br><b>Power</b>   | Fuel<br><b>Oil and Gas</b>  | Method of Firing<br><b>Automatic</b>  | Pressure Gage Tested<br><input type="checkbox"/> Yes <input checked="" type="checkbox"/> No |  |
| Pressure Allowed<br><b>150</b>  | This Inspection<br><b>150</b> psi | Prev. Inspection<br><b>150</b> psi  | Safety Relief Valves Set At<br><b>90</b> psi  | Total Capacity<br><b>8354 LB/HR</b>   | Heating Surface and/or BTU<br><b>1000 sq ft / 6900000 BTU/hr</b>                            |  |
| Is condition of object such that a certificate may be issued?<br>(If No, explain fully under condition)   |                                   |   |   | Hydro Test<br><input type="checkbox"/> Yes <input checked="" type="checkbox"/> No |   |  |
| <p><b>CONDITIONS:</b> With respect to the internal surface, describe and state location of any scale, oil or other deposits. Give location and extent of any corrosion and state whether active or inactive. State location and extent of any erosion, grooving, bulging, warping, cracking or similar condition. Report on any defective rivets, bowed, loose or broken stays. State condition of all tubes, tube ends, coils, nipples, etc. Describe any adverse conditions with respect to pressure gage, water column, gage glass, gage cocks, safety valves, etc. Report conditions of setting, linings, baffles, supports, etc. Describe any major changes or repairs made since last inspection.</p> <p><b>Witnessed manual testing of the following safety devices: Primary low water fuel cutoff, auxiliary low water fuel cutoff, flame failure device, and low gas pressure switch. No adverse conditions noted. Request certificate be issued. Inspection being done early to align certificate expiration dates.</b></p> |                                   |   |   |   |   |  |
| <p><b>REQUIREMENTS:</b> (List of Code Violations)</p> <p><b>None Required</b></p>   |                                   |   |   |   |   |  |
| Name and Title of Person To Whom Requirements Were Explained<br>Bill Shumaker, Facilities Technician  |                                   |   |   |   |   |  |
| I HEREBY CERTIFY THIS IS A TRUE REPORT OF MY INSPECTION<br><i>Victor R. Casada</i>  |                                   |   |   |   |   |  |
| Inspector Name<br><b>Victor Casada</b>  |                                   | Ident. No.<br><b>FL-0516 NB-10971</b>   |   | Employed By<br><b>Zurich American Insurance Co</b>                                |   | Ident. No.<br><b>30199766</b>  |

**D14-379  
10/01/2000**