

**DIVISION OF THE STATE FIRE MARSHALL
BUREAU OF FIRE PREVENTION
BOILER SAFETY PROGRAM**

This inspection is intended for your safety and the safety of the citizens of Florida. Your cooperation is greatly appreciated.

Boiler - Fired Pressure Vessel report of Inspection

Date Inspected 12/11/2025	Cert. Exp Date	Certificate Posted <input type="checkbox"/> Yes <input type="checkbox"/> No	Follow Up Inspection <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Jurisdiction Number 025576	Nat'l Bd. No. 13979	Other No.
Owner Tailored Brands			Owner Email maintenanceinvoices@tailoredbrands.com		Kind of Inspection <input checked="" type="checkbox"/> Int <input type="checkbox"/> Ext	Cert Inspection <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Owner Street Address 5601 Arnold Rd Ste 200			Owner City Dublin		State CA	Zip 94568-7724
User Name - Object Location Men's Wearhouse #3319			Nature Of Business Retail		Object Location - County Hillsborough	
User Street Address 8009 Citrus Park Dr			User City Tampa		State FL	Zip 33625-3001
Type Miniature	ASME Code Stamp M	Year Built 2017	Manufacturer Pacific			
Specific Location in Plant Tailor Shop		Use Process	Fuel Natural Gas	Method of Firing Automatic	Pressure Gage Tested <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Pressure Allowed 100	This Inspection 100 psi	Prev. Inspection 100 psi	Safety Relief Valves Set At 100 psi	Total Capacity 423 LB/HR	Heating Surface and/or BTU 61000 BTU/hr	
Is condition of object such that a certificate may be issued? (If No, explain fully under condition)				Hydro Test <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		
<p>CONDITIONS: With respect to the internal surface, describe and state location of any scale, oil or other deposits. Give location and extent of any corrosion and state whether active or inactive. State location and extent of any erosion, grooving, bulging, warping, cracking or similar condition. Report on any defective rivets, bowed, loose or broken stays. State condition of all tubes, tube ends, coils, nipples, etc. Describe any adverse conditions with respect to pressure gage, water column, gage glass, gage cocks, safety valves, etc. Report conditions of setting, linings, baffles, supports, etc. Describe any major changes or repairs made since last inspection.</p> <p>BVI for Tailored Brands. Performed an internal inspection of the boiler in accordance with ASME, NBIC, and Jurisdictional codes and standards. Installation of controls and safety devices were verified, boiler watersides were inspected and in acceptable condition at this time. Boiler elements were inspected and found no major damage on elements, LWCO probes, blow down lines or clean outs, access ports were clear of build-up and in acceptable condition, verified relief valve installation and information, and boiler room conditions and requirements were verified.</p>						
<p>REQUIREMENTS: (List of Code Violations)</p> <p>None Required</p>						
Name and Title of Person To Whom Requirements Were Explained Tailor Staff						
I HEREBY CERTIFY THIS IS A TRUE REPORT OF MY INSPECTION						
Inspector Name Nathan Beck		Ident. No. FL-25-001190 NB-20108		Employed By BVI&I		Ident. No. 30284268

**D14-379
10/01/2000**